

004	Subase Kings Bay, Georgia		Waste Information Document (WID)	
As of 1/23/2020			WID Number 1263 - 004	
Waste Description: LUBRICANT, SOLID DRY FILM				
Waste Material label required?: YES			Hazardous Waste label required?: YES	
Waste Generation Process: PREVENTATIVE MAINTENANCE ON SUPPORT EQUIPMENT. USED OR UNUSED MATERIAL.				
Waste Class: HAZARDOUS WASTE			Required Container: STEEL / POLY	
EPA Waste Numbers D001,D008,D035,F005				
Special Handling & Instructions: UHC: NONE				
Remarks GHS02, GHS07, GHS08				
For Environmental Department Use Only - - - - Material Composition				
Component		Percent	Parts Per Million	
1. METHYL ETHYL KETONE		65%	650000 ppm	
2. TOLUENE		15%	150000 ppm	
3. LEAD PHOSPHITE		15%	150000 ppm	
4. ETHYL BENZENE		5%	50000 ppm	
5.		%	ppm	
Physical State: LIQUID	Waste Water: NO	Toxic: YES	Dioxin Listed: NO	
Corrosive: NO	pH: N/A	Reactive: NO	Flash Point: 24 F.	
High TOC:	Low TOC :	Land Ban: YES	Flammable: YES	
Reason for Classification: FLASH POINT = 24 DEGREES F. CONTAINS LEAD PHOSPHITE, METHYL ETHYL KETONE, AND TOLUENE.				
Treatment Standards: 40 CFR 261		CAS# MIXTURE	Generation Code: G06	
Shipping Information				
DOT Shipping Name: UN1263, WASTE PAINT RELATED MATERIAL (LEAD, METHYL ETHYL KETONE, TOLUENE) 3, PGII, D001, D008, D035, F005				
HAZ Class: 3	Reportable Quantity: 10 LBS.		Emergency Response Guide #: 128	
EPA Waste Numbers: D001,D008,D035,F005				
Certification: I certify that the above named materials are the only compounds included in the waste stream described and no other substance is present.		<div style="display: flex; justify-content: space-between;"> <div> Prepared by  Signed and Dated Copy On File </div> <div> Subase Env. Rep  Review/Signature </div> </div>		