

006	Subase Kings Bay, Georgia		Waste Information Document (WID)	
As of 6/9/2022			WID Number 1263 - 006	
Waste Description: PITTHANE PART A&B				
Waste Material label required?: YES			Hazardous Waste label required?: YES	
Waste Generation Process: PAINT WASTE IS GENERATED AT EHW-1 FROM LEFT OVER PAINT THINNING PAINT AND CLEANING VARIOUS APPARATUS				
Waste Class: HAZARDOUS WASTE			Required Container: STEEL / POLY	
EPA Waste Numbers D001, D005				
Special Handling & Instructions: UHC: MALEIC ANHYDRIDE				
Remarks FEAD CONTRACTOR GHS02 ,GHS08				
For Environmental Department Use Only - - - - Material Composition				
Component		Percent		Parts Per Million
1. BARIUM SULFATE		8-24%		80000-240000ppm
2. CRYSTALLINE SILICA RESPIRABLE POWDER		.08 - .8%		800-8000ppm
3. HEPTANE-2-ONE		8-24%		80000-240000ppm
4. HEXAMETHYLENE DIISOCYANATE OLIGOMERS		72%		720000ppm
5. TITANIUM DIOXIDE		8-24%		80000-240000ppm
Physical State: LIQUID	Waste Water: NO	Toxic: YES		Dioxin Listed: NO
Corrosive: NO	pH: 7	Reactive: NO		Flash Point: 73-100F
High TOC:	Low TOC :	Land Ban: YES		Flammable: YES
Reason for Classification: FLASH POINT 73-100F CONTAINS BARIUM PER WASTE PROFILE #2326976				
Treatment Standards: 40 CFR 261		CAS# N/A		Generation Code: G06
Shipping Information				
DOT Shipping Name: UN1263, WASTE PAINT RELATED MATERIAL, 3, PGIII, D001,D005				
HAZ Class: 3		Reportable Quantity: 100 LBS.		Emergency Response Guide #: 128
EPA Waste Numbers: D001, D005				
Certification: I certify that the above named materials are the only compounds included in the waste stream described and no other substance is present.		<div>Prepared by</div> <div>Signed and Dated Copy On File _____</div> <div>Subase Env. Rep</div> <div>Review/Signature_____</div>		