

010	Subase Kings Bay, Georgia		Waste Information Document (WID)	
As of 4/5/2021			WID Number 1263 - 010	
Waste Description: BITUMASTIC 50 COAL-TAR COATING				
Waste Material label required?: YES			Hazardous Waste label required?: YES	
Waste Generation Process: MATERIAL IN OPENED OR DAMAGED CONTAINERS.				
Waste Class: HAZARDOUS WASTE			Required Container: POLY/STEEL	
EPA Waste Numbers D001, D018, D026				
Special Handling & Instructions:				
Remarks GHS02, GHS08				
For Environmental Department Use Only - - - - Material Composition				
Component		Percent		Parts Per Million
1. COAL-TAR PITCH		50-<75%		500000-<750000ppm
2. META-XYLENE & PARA-XYLENE		2.5-<10%		25000-<100000ppm
3. ETHYL BENZENE		2.5-<10%		25000-<100000ppm
4. ORTHO-XYLENES		2.5-<10%		25000-<100000ppm
5. SURFACTANT		1-<2.5%		10000-<25000ppm
Physical State: LIQUID	Waste Water: NO	Toxic: YES		Dioxin Listed: NO
Corrosive: NO	pH: N/A	Reactive: NO		Flash Point: 80 F.
High TOC:	Low TOC :	Land Ban: YES		Flammable: YES
Reason for Classification: CREOSOTE 7.5-30% BENZENE 2.5-10% FLASH POINT 80 F.				
Treatment Standards: 40 CFR 261		CAS# MIXTURE	Generation Code: G11	
Shipping Information				
DOT Shipping Name: UN1263, WASTE PAINT, 3, PGIII, D001, D018, D026				
HAZ Class: 3	Reportable Quantity: 10 LBS.		Emergency Response Guide #: 128	
EPA Waste Numbers: D001, D018, D026				
Certification: I certify that the above named materials are the only compounds included in the waste stream described and no other substance is present.		<div style="display: flex; justify-content: space-between;"> <div> Prepared by _____ Signed and Dated Copy On File ____ </div> <div> Subase Env. Rep _____ Review/Signature_____ </div> </div>		