

038	Subase Kings Bay, Georgia		Waste Information Document (WID)	
As of 4/12/2022			WID Number 1307 - 038	
Waste Description: MIXED XYLENES (USED)				
Waste Material label required?: YES			Hazardous Waste label required?: YES	
Waste Generation Process: EXCESS MATERIAL, EXPIRED SHELF LIFE MATERIAL, IN OPEN OR DAMAGED CONTAINERS.				
Waste Class: HAZARDOUS WASTE			Required Container: STEEL / POLY	
EPA Waste Numbers D001				
Special Handling & Instructions: UHC: ETHYLBENZENE, TOLUENE				
Remarks GHS02, GHS07, GHS08				
For Environmental Department Use Only - - - - Material Composition				
Component		Percent		Parts Per Million
1. XYLENE		>=78-<79%		>=780000-<790000ppm
2. ETHYL BENZENE		>=20-<21%		>=200000-<210000ppm
3. TOLUENE		>=.1-<1%		>=1000-<10000ppm
4. CUMENE		>=.1-<1%		>=1000-<10000ppm
5.		%		ppm
Physical State: LIQUID	Waste Water: NO	Toxic: YES		Dioxin Listed: NO
Corrosive: NO	pH: N/A	Reactive: NO		Flash Point: 8I
High TOC:	Low TOC :	Land Ban: YES		Flammable: YES
Reason for Classification: FLASH POINT 81 F., BENZENE, SPENT SOLVENT.				
Treatment Standards: 40 CFR 261		CAS# N/A	Generation Code: G11	
Shipping Information				
DOT Shipping Name: UN1307, WASTE XYLENES, 3, PGIII, D001				
HAZ Class: 3	Reportable Quantity: 100 LBS.		Emergency Response Guide #: 130	
EPA Waste Numbers: D001				
Certification: I certify that the above named materials are the only compounds included in the waste stream described and no other substance is present.		<div style="display: flex; justify-content: space-between;"> <div> Prepared by _____ Signed and Dated Copy On File ____ </div> <div> Subase Env. Rep _____ Review/Signature_____ </div> </div>		