

052	Subase Kings Bay, Georgia		Waste Information Document (WID)	
As of 2/16/2021			WID Number 2924 - 052	
Waste Description: PAINT WASTE FROM CHRIMP CENTERS-(ACID)				
Waste Material label required?: YES			Hazardous Waste label required?: YES	
Waste Generation Process: UNUSED OR EXCESS PAINT RETURNED TO CHRIMP CENTER FROM SHOPS FOR PROCESSING. MAY BE CORROSIVE. (Ph =<2.0)				
Waste Class: HAZARDOUS WASTE			Required Container: POLY	
EPA Waste Numbers D001,D002				
Special Handling & Instructions: FOR TWO PART PAINT KIT WHERE ONE PART IS EQUAL TO OR LESS THAN A pH OF 2.0. UHC: METHYL ISOBUTYL KETONE				
Remarks i.e. TRILON COATINGS INC., C-152-66 ACID COMPONENT GHS02, GHS05, GHS09				
For Environmental Department Use Only - - - - Material Composition				
Component		Percent	Parts Per Million	
1. ETHYL ALCOHOL		25-50%	250000-500000ppm	
2. WATER		15-20%	150000-200000ppm	
3. PHOSPHORIC ACID		15-20%	150000-200000ppm	
4. METHYL ALCOHOL		5-10%	50000-100000ppm	
5. METHYL ISOBUTYL KETONE		5-10%	50000-100000ppm	
Physical State: LIQUID	Waste Water: NO	Toxic: YES	Dioxin Listed: NO	
Corrosive: YES	pH: (<=)2	Reactive: NO	Flash Point: 60	
High TOC:	Low TOC :	Land Ban: YES	Flammable: YES	
Reason for Classification: FLASH POINT <140 DEGREES F., CORROSIVE PH 2.0 OR LOWER				
Treatment Standards: 40 CFR 261		CAS# MIXTURE	Generation Code: G06	
Shipping Information				
DOT Shipping Name: UN2924, WASTE FLAMMABLE LIQUID, CORROSIVE, NOS, (ETHANOL, PHOSPHORIC ACID) 3 (8), PGII, D001,D002				
HAZ Class: 3 (8)	Reportable Quantity: 10 LBS.		Emergency Response Guide #: 128	
EPA Waste Numbers: D001,D002				
Certification: I certify that the above named materials are the only compounds included in the waste stream described and no other substance is present.		<div style="display: flex; justify-content: space-between;"> <div> Prepared by Signed and Dated Copy On File </div> <div> Subase Env. Rep Review/Signature </div> </div>		