053 Subase Kings Bay, Georgia		Waste In	Waste Information Document (WID)			
As of 6/7/2022			WI	D Numbe	er 1760 - 053	
Waste Description: PAINT	WITH LISTED SOLVE	ENTS, CO	ORROSIVE, METH	YL ETHY	L KETONE	
Waste Material label required?: YES			Hazardous Waste label required?: YES			
Waste Generation Process: P	AINT WASTE AND L	ISTED S	OLVENTS, MAY B	E CORRO	OSIVE.	
Waste Class: HAZARDOUS WASTE			Required Container: POLY			
EPA Waste Numbers D001,	D002, D035, F003, F0	005				
Special Handling & Instruction THAN A pH OF 12.5. FAST- INCLUDING FAST CLAD E	CLAD ER EPOXY (F		SHERWIN WILLIA			
Remarks LIQUID ONLY. GHS02, GHS05, GHS08					GHS05, GHS08	
For E	nvironmental Departr	nent Use	Only Mater	al Compo	osition	
Component			Percent		Parts Per Million	
1. SOLVENTS: METHYL ETHYL KETONE, XYLEN TOLUENE			65%		650000ppm	
2. PAINTS			<18.7%		<187000ppm	
3. TRIMETHYL-1,6-HEXANEDIAMINE			>8.2%		>82000ppm	
4. 1,3-BENZENEDIMETHANAMINE			>8%		>80000ppm	
5.			%		ppm	
Physical State: LIQUID	Waste Water: NO		Toxic: YES		Dioxin Listed: NO	
Corrosive: YES	pH: 12.5		Reactive: NO		Flash Point: <140	
High TOC:			Land Ban: YES		Flammable: YES	
Reason for Classification: FL SOLVENTS	ASH POINT <140 DE	EGREES I	F., CORROSIVE 12.	5 OR HIG	HER, AND LISTED	
Treatment Standards: 40 CFR 261		CAS	# SOLUTION	Generation Code: G06		
	Shi	ipping In	formation			
DOT Shipping Name: UN29 D002, D035, F003, F005	20, WASTE CORROS	IVE LIQU	JIDS, FLAMMABL	E, NOS (A	AMINE) 8 (3), PGII D001,	
HAZ Class: 8(3) Reportable Qu		Quantity	antity: 100 LBS.		Emergency Response Guide #: 132	
EPA Waste Numbers: D001,	D002, D035, F003, F0	005				
Certification: I certify that the are the only compounds includescribed and no other substa	ded in the waste stream	ı	Prepared by ed and Dated Copy (— On File	Subase Env. Rep Review/Signature	