

153	Subase Kings Bay, Georgia		Waste Information Document (WID)	
As of 10/21/2020			WID Number 1223 - 153	
Waste Description: KEROSENE				
Waste Material label required?: YES			Hazardous Waste label required?: YES	
Waste Generation Process: THIS LOW FLASH POINT CLEANING SOLVENT RECEIVED FOR DISPOSAL AS HAZARDOUS WASTE. MATERIAL HAS EXPIRED SHELF, LIFE IN OPEN OR DAMAGED CONTAINERS. TO INCLUDE FUEL ADDITIVES				
Waste Class: HAZARDOUS WASTE			Required Container: STEEL / POLY	
EPA Waste Numbers D001				
Special Handling & Instructions: UHC: BENZENE, XYLENE				
Remarks GHS02, GHS06, GHS07, GHS09				
For Environmental Department Use Only - - - - Material Composition				
Component		Percent	Parts Per Million	
1. NAPHTHA, PETROLEUM, HYDROTREATED HEAVY		90%	900000 ppm	
2. OCTYLPHENYOL ETHOXYLATE		9.7%	97000 ppm	
3. POLYETHYLENE GLYCOL		0%	ppm	
4.		%	ppm	
5.		%	ppm	
Physical State: LIQUID	Waste Water: NO	Toxic: NO	Dioxin Listed: NO	
Corrosive: NO	pH: N/A	Reactive: NO	Flash Point: 100 F.	
High TOC:	Low TOC :	Land Ban: YES	Flammable: YES	
Reason for Classification: FLASH POINT = 100 DEGREES F.				
Treatment Standards: 40 CFR 261		CAS# MIXTURE	Generation Code: G11	
Shipping Information				
DOT Shipping Name: UN1223, WASTE KEROSENE 3, PGIII, D001				
HAZ Class: 3	Reportable Quantity: 100 LBS.		Emergency Response Guide #: 128	
EPA Waste Numbers: D001				
Certification: I certify that the above named materials are the only compounds included in the waste stream described and no other substance is present.		<div style="display: flex; justify-content: space-between;"> <div> Prepared by Signed and Dated Copy On File </div> <div> Subase Env. Rep Review/Signature </div> </div>		