

213	Subase Kings Bay, Georgia		Waste Information Document (WID)	
As of 4/19/2022			WID Number 1090 - 213	
Waste Description: DECACHLOROBIPHENYL				
Waste Material label required?: YES			Hazardous Waste label required?: YES	
Waste Generation Process: EXCESS MATERIAL, EXPIRED SHELF LIFE MATERIAL, IN OPEN OR DAMAGED CONTAINERS.				
Waste Class: HAZARDOUS WASTE			Required Container: POLY DRUM	
EPA Waste Numbers D001				
Special Handling & Instructions:				
Remarks GHS02,GHS07				
For Environmental Department Use Only - - - - Material Composition				
Component		Percent		Parts Per Million
1. ACETONE		>=90-<=100%		>=900000-<=1000000ppm
2. DECACHLORO-1,1'-BIPHENYL		<0.1%		<1000ppm
3.		%		ppm
4.		%		ppm
5.		%		ppm
Physical State: LIQUID	Waste Water: NO	Toxic: YES	Dioxin Listed: NO	
Corrosive: NO	pH: N/A	Reactive: NO	Flash Point: <140 F.	
High TOC:	Low TOC :	Land Ban: YES	Flammable: YES	
Reason for Classification: SDS: HIGHLY FLAMMABLE LIQUID				
Treatment Standards: 40 CFR 261		CAS# MIXTURE	Generation Code: G11	
Shipping Information				
DOT Shipping Name: UN1090, WASTE ACETONE SOLUTION, 3, PGII, D001				
HAZ Class: 3	Reportable Quantity: 100 LBS.		Emergency Response Guide #: 127	
EPA Waste Numbers: D001				
Certification: I certify that the above named materials are the only compounds included in the waste stream described and no other substance is present.		<div style="display: flex; justify-content: space-between;"> <div> Prepared by _____ Signed and Dated Copy On File ____ </div> <div> Subase Env. Rep _____ Review/Signature_____ </div> </div>		