

570	Subase Kings Bay, Georgia		Waste Information Document (WID)	
As of 2/15/2018			WID Number 3082 - 570	
Waste Description: SILVER RECOVERY CARTRIDGE (SPENT)				
Waste Material label required?: YES			Hazardous Waste label required?: YES	
Waste Generation Process: FILM PROCESSING MACHINE DISCHARGE FLOWS THROUGH SILVER RECOVERY CARTRIDGES. FLAKED SILVER ACCUMULATES INSIDE CARTRIDGES UNTIL THEY ARE INEFFECTIVE. FILTERS CONTAIN WATER AND SPENT FILM-PROCESSING CHEMICALS. INCLUDES SPENT SILVER RECOVERY CARTRIDGES FROM ALL COMMANDS.				
Waste Class: HAZARDOUS WASTE			Required Container: STEEL / POLY	
EPA Waste Numbers D011				
Special Handling & Instructions: UHC: NONE				
Remarks GHS07				
For Environmental Department Use Only - - - - Material Composition				
Component		Percent	Parts Per Million	
1. PLASTIC/METAL CARTRIDGES		50%	500000 ppm	
2. WATER		40%	400000 ppm	
3. NON-RCRA CHEMICALS		5%	50000 ppm	
4. SILVER SALTS AND SILVER		5%	50000 ppm	
5.		%	ppm	
Physical State: LIQUID	Waste Water: NO	Toxic: YES	Dioxin Listed: NO	
Corrosive: NO	pH: 6.00	Reactive: NO	Flash Point: N/A	
High TOC:	Low TOC :	Land Ban: YES	Flammable: NO	
Reason for Classification: TCLP SILVER >5.0 PPM				
Treatment Standards: 40 CFR 261		CAS# MIXTURE	Generation Code: G07	
Shipping Information				
DOT Shipping Name: NA3082, HAZARDOUS WASTE LIQUID, NOS (SILVER SALTS) 9, PGIII, D011				
HAZ Class: HAZARDOUS WASTE	Reportable Quantity: 1 LBS.		Emergency Response Guide #: 171	
EPA Waste Numbers: D011				
Certification: I certify that the above named materials are the only compounds included in the waste stream described and no other substance is present.		<div style="display: flex; justify-content: space-between;"> <div> Prepared by Signed and Dated Copy On File </div> <div> Subase Env. Rep Review/Signature </div> </div>		