627	Subase Kings Bay, Georgia				Waste Information Document (WID)			
As of 1/	of 1/27/2025				WID Number 2924 - 627			
Waste Description: TETRA-ETCH ETCHANT								
Waste Material label required?: YES					Hazardous Waste label required?: YES			
Waste Generation Process: EXCESS MATERIAL, EXPIRED SHELF-LIFE, IN OPEN OR DAMAGED CONTAINERS.								
Waste Class: HAZARDOUS WASTE				R	Required Container: STEEL / POLY			
EPA Waste Numbers D001, D003								
Special Handling & Instructions: UHC: NONE								
Remarks GHS02, GHS05, GHS07, GHS08, GHS09  For Environmental Department Use Only Material Composition								
Component  1. 1,2 DIMETHOXYETHANE					~70%		~700000ppm	
2. NAPHTHALENE					25%		250000ppm	
3. SODIUM METAL					5%		50000ppm	
4.					%		ppm	
5.					%		ppm	
Physical State: LIQUID Waste Water: NO			Te	Toxic: YES		Dioxin Listed: NO		
Corrosive	Corrosive: NO pH: N/A			R	Reactive: YES		Flash Point: 32	
High TO	igh TOC: Low TOC:			L	Land Ban: YES		Flammable: YES	
Reason for Classification: SDS FL PT. 32 F REACTS WITH WATER TO FORM SODIUM HYDROXIDE AND NAPHTHALENE SMALL QUANTITIES HYDROGEN EVOLVED								
Treatment Standards: 40 CFR 261				CAS#	CAS# N/A		Generation Code: G11	
Shipping Information								
DOT Shipping Name: UN2924, WASTE FLAMMABLE LIQUID, CORROSIVE, NOS(CONTAINS 1,2 DIMETHOXYETHANE) 3, PGII, D001, D003								
HAZ Class: 3 Reportable			Reportable Qu	Quantity: 100 LBS.		Emergency Response Guide #: 128		
EPA Waste Numbers: D001, D003								
Certification: I certify that the above named materials are the only compounds included in the waste stream described and no other substance is present.  Prepared by Subase Env. Rep Signed and Dated Copy On File Review/Signature								