047 <b>Sul</b>	Subase Kings Bay, Georgia				Waste Information Document (WID)			
As of 5/11/2	021				WID Number 3077 - 047			
Waste Description: PAINT RELATED ITEMS/DEBRIS (NRMD)								
Waste Material label required?: YES					Hazardous Waste label required?: YES			
PREPARATION CHROMIUM	ON/PAINTING	PROCESS CEEDING	S WHICH MAY	BE CO		WITH BA	ENERATED DURING RIUM, CADMIUM, ITEMS/DEBRIS	
Waste Class: HAZARDOUS WASTE					Required Container: STEEL / POLY			
EPA Waste N	umbers D005,I	D006,D007	7, D008					
Special Handling & Instructions: ONE OR MORE OF THESE EPA WASTE CODES MAY APPLY. NO FREE LIQUIDS ALLOWED IN CONTAINERS.  UHC: NONE  Remarks GHS07, GHS08, GHS09								
For Environmental Department Use Only Material Composition								
Component					Percent		Parts Per Million	
1. DEBRIS/ITEMS					95%		950000ppm	
2. CADMIUM, CHROMIUM, BARIUM, LEAD					5%		50000ppm	
3.					%		ppm	
4.					%		ppm	
5.					%		ppm	
Physical State: SOLID Waste Water: NO				Toxic: YES			Dioxin Listed: NO	
Corrosive: No	0	pH: N/A	1	R	Reactive: NO		Flash Point: N/A	
High TOC:					Land Ban: YES		Flammable: NO	
Reason for Cl LIMITS	assification: TC	LP LISTE	D CONTAMIN	NANTS	GREATER THAN	N REGULA	ATORY PERMISSIBLE	
Treatment Standards: 40 CFR 261				CAS# MIXTURE General		Genera	ntion Code: G06	
			Shipp	ing Info	ormation			
	g Name: NA307 5, D006, D007, l		RDOUS WAST	E SOL	D, NOS(BARIUN	I, CADMI	UM, CHROMIUM, LEAD)	
HAZ Class: 9			Reportable Quantity:		N/A LBS.	Emergen	cy Response Guide #: 171	
EPA Waste N	umbers: D005,D	0006,D007	, D008					
Certification: I certify that the above named materials are the only compounds included in the waste stream described and no other substance is present.					Prepared by I and Dated Copy	 On File	Subase Env. Rep Review/Signature	