552	Subase Kings Bay, Georgia			Waste Information Document (WID)				
As of 7/13/2009					WI	D Numbe	r 5052 - 552	
Waste Description: POTASSIUM CARBONATE SOLUTION								
Waste Material label required?: YES					Hazardous Waste label required?: NO			
	eneration Process: A SSION AGENT, US			F POTA	ASSIUM CARBON	IATE, WH	IICH ACTS AS A FIRE	
Waste Class: NON HAZARDOUS WASTE					Required Container: STEEL / POLY			
EPA Waste Numbers NONE								
Special H	Iandling & Instructio	ns: TRAN	SPORT TO IW	TF FOF	R TREATMENT			
Remarks English and the Only Matrial Company in the Control of th								
For Environmental Department Use Only Material Composition								
Component					Percent		Parts Per Million	
1. POTASSIUM CARBONATE					50%		500000ppm	
2. WATER					50%		500000ppm	
3. 4.				%		ppm		
5.					%		ppm	
Physical State: LIQUID Waste Water: NO				т	Toxic: NO		ppm Dioxin Listed: NO	
	orrosive: NO pH: 9.0				Reactive: NO		Flash Point: N/A	
High TO	1				Land Ban: NO		Flammable: NO	
Reason for Classification: NON LISTED, NON CHARACTERISTIC								
Treatment Standards: 40 CFR 261				CAS#	CAS# SOLUTION		Generation Code: G11	
Shipping Information								
DOT Shipping Name: POTASSIUM CARBONATE SOLUTION								
HAZ Class: NONE Reportable C			Reportable Qu	uantity: N/A LBS.		Emergency Response Guide #: N/A		
EPA Waste Numbers: NONE								
Certification: I certify that the above named materials are the only compounds included in the waste stream described and no other substance is present. Prepared by Subase Env. Rep Signed and Dated Copy On File Review/Signature								