575 Subase Kings Bay, Georgia				Waste Information Document (WID)		
As of 6/6/2013				W	ID Number	r 5021 - 575
Waste Description: NDT RINSE WATER						
Waste Material label required?: YES				Hazardous Waste label required?: NO		
Waste Generation Process: VARIOUS NON DESTRUCTIVE TESTING (NDT) PENETRANTS AND DEVELOPERS ARE APPLIED TO EQUIPMENT AND PARTS FOR NDT INSPECTIONS. THE WASTE FROM THESE PROCESSES INCLUDES RINSE WATER ALONG WITH MINIMAL AMOUNTS OF PENETRANTS AND DEVELOPER. SHOP RAGS AND WIPES ARE USED THROUGHOUT THE PROCESS AND ARE INCLUDED AS PART OF THIS WASTE STREAM.						
Waste Class: NON HAZARDOUS WASTE			Required Container: STEEL / POLY			
EPA Waste Numbers NONE						
Special Handling & Instructions:						
Remarks						
For Environmental Department Use Only Material Composition						
Component				Percent		Parts Per Million
1. VARIOUS NDT PENETRANTS AND DEVELOPERS			ERS	1%		10000ppm
2. SHOP RAGS				8%		80000ppm
3. RINSE WATER				91%		910000ppm
4.				%		ppm
5.				%		ppm
Physical State: LIQUID	Waste Water: NO		Т	Toxic: NO		Dioxin Listed: NO
Corrosive: NO	pH: 7.22		Reactive: N0			Flash Point: N/A
High TOC: Low TOC :		Land Ban: NO			Flammable: NO	
Reason for Classification: NON LISTED, NON CHARACTERISTIC						
Treatment Standards: 40 CFR 261		CAS# MIXTURE		Generation Code: G09		
Shipping Information						
DOT Shipping Name: NON REGULATED LIQUID						
HAZ Class: NONE Rep		Reportable Qu	Reportable Quantity: N/A LBS.		Emergency Response Guide #: N/A	
EPA Waste Numbers: NONE						
						Subase Env. Rep Review/Signature