009 Subase Kings Bay, Georgia		Waste Information Document (WID)				
As of 12/7/2017			WI	D Numbe	er 1268 - 009	
Waste Description: MINER	AL SPIRITS					
Waste Material label required?: YES			Hazardous Waste label required?: YES			
Waste Generation Process: NINCLUDES MATERIAL WINDER POLISHES AND OTHER P.	ITH EXPIRED SHELF LI	FE, IN (OPEN OR DAMAC			
Waste Class: HAZARDOUS WASTE			Required Container: STEEL / POLY			
EPA Waste Numbers D001		•				
Special Handling & Instructi	ons:					
Remarks GHS02, GHS08	Santana mantal Dan auton a	A Ugo C	Noto:	al Camp	oo!4: or	
	Environmental Departmer	it Use C	Percent	ai Comp	Parts Per Million	
Component 1. MINERAL SPIRITS			53%		530000 ppm	
2. NON-RCRA HYDROCARBONS			47%		470000 ppm	
3.			%		ppm	
4.			%		ppm	
5.			%		ppm	
Physical State: LIQUID	Waste Water: NO	Г	Toxic: NO		Dioxin Listed: NO	
Corrosive: NO	pH: N/A	A R			Flash Point: <140F	
High TOC:	Low TOC:	I	Land Ban: YES		Flammable: YES	
Reason for Classification: F	LASH POINT <140 DEGR	REES°1	3			
Treatment Standards: 40 CFR 261		CAS# SOLUTION		Generation Code: G06		
	Shipp	ing Info	ormation			
DOT Shipping Name: UN12	268, WASTE PETROLEUN	M DIST	ILLATES, NOS (M	IINERAI	L SPIRITS) 3, PGIII, D001	
HAZ Class: HAZARDOUS WASTE Reportable Qua			antity: 100 LBS. Emergen		cy Response Guide #: 128	
EPA Waste Numbers: D001						
Certification: I certify that the compounds includes and no other substants.	aded in the waste stream		Prepared by d and Dated Copy (— On File _	Subase Env. Rep Review/Signature	