032	32 Subase Kings Bay, Georgia				Waste Information Document (WID)			
As of 1	/14/2015				W	ID Number	5000 - 032	
Waste D	escription: PAINT	REMOVE	₹					
Waste Material label required?: YES					Hazardous Waste label required?: NO			
	eneration Process: U GED CONTAINERS.		JSED PAINT R	EMOVE	R SOLUTION. 1	EXPIRED S	HELF LIFE, IN OPEN OR	
Waste Class: NON-RCRA				Required Container: STEEL / POLY				
EPA Wa	ste Numbers NONE	Į.		•				
-	Handling & Instruction		V-GEL AND A	NY OTH	FR NON-LISTE	D NON CH	ARACTERISTIC PAINT	
	ER, STRIPPER OR	THINNER	AND DEBRIS					
For Environmental Department Use Only Material Composition Component Percent Parts Per Milli							Parts Per Million	
1. NON-RCRA INGREDIENTS					100%		1000000 ppm	
2.					%		ррт	
3.					%		ppm	
4.					%		ppm	
5.					%		ppm	
Physical State: LIQUID Waste Water: NO				Toxic: NO			Dioxin Listed: NO	
Corrosiv	prrosive: NO pH: 6.8			Reactive: NO			Flash Point: >140 F.	
High TO	High TOC: Low TOC:			Land Ban: NO			Flammable: NO	
Reason f	or Classification: No	ON LISTE	D, NON CHAR	ACTER	ISTIC			
Treatment Standards: 40 CFR 261			CAS# 1	CAS# MIXTURE		Generation Code: G11		
			Shippi	ing Info	mation	•		
DOT Sh	pping Name: NON	REGULAT	TED LIQUID					
HAZ Class: NON-RCRA Reportable Q			antity: N/A LBS.		Emergency Response Guide #: N/A			
EPA Wa	ste Numbers: NONE							
Certification: I certify that the above named materials are the only compounds included in the waste stream described and no other substance is present.					Prepared by and Dated Copy	— On File	Subase Env. Rep Review/Signature	