

299	Subase Kings Bay, Georgia		Waste Information Document (WID)	
As of 9/13/2018			WID Number 3077 - 299	
Waste Description: SOLVENT RAGS AND DEBRIS				
Waste Material label required?: YES			Hazardous Waste label required?: YES	
Waste Generation Process: VARIOUS PROCESSESS WHERE SOLVENTS ARE USED IN CLEANING AND DEGREASING. INCLUDES ACETONE, ETHYL BENZENE, METHANOL, TOLUENE, XYLENE AND OTHER LISTED SOLVENT.				
Waste Class: HAZARDOUS WASTE			Required Container: STEEL / POLY	
EPA Waste Numbers F001, F002, F003,F005				
Special Handling & Instructions: NO FREE LIQUIDS				
Remarks GHS06, GHS07, GHS08				
For Environmental Department Use Only - - - - Material Composition				
Component		Percent	Parts Per Million	
1. RAGS AND DEBRIS		95%	950000 ppm	
2. LISTED SOLVENTS		5%	50000 ppm	
3.		%	ppm	
4.		%	ppm	
5.		%	ppm	
Physical State: SOLID	Waste Water: NO	Toxic: YES	Dioxin Listed: NO	
Corrosive: NO	pH: N/A	Reactive: NO	Flash Point: N/A	
High TOC:	Low TOC :	Land Ban: YES	Flammable: NO	
Reason for Classification: CONTAINS LISTED SOLVENTS GREATER THAN 10% BEFORE USE				
Treatment Standards: 40 CFR 261		CAS# MIXTURE	Generation Code: G07	
Shipping Information				
DOT Shipping Name: NA3077, HAZARDOUS WASTE SOLID NOS (ACETONE,METHANOL,TOLUENE,XYLENE) 9, PGIII, F001,F002,F003,F005				
HAZ Class: HAZARDOUS WASTE	Reportable Quantity: 1000 LBS.		Emergency Response Guide #: 171	
EPA Waste Numbers: F001, F002, F003,F005				
Certification: I certify that the above named materials are the only compounds included in the waste stream described and no other substance is present.		<div style="display: flex; justify-content: space-between;"> <div> Prepared by  Signed and Dated Copy On File </div> <div> Subase Env. Rep  Review/Signature </div> </div>		