

598	Subase Kings Bay, Georgia		Waste Information Document (WID)	
As of 4/25/2022			WID Number 2206 - 598	
Waste Description: FIREX, RX-2376, PART A OF TWO PART URETHANE RESIN SYSTEM				
Waste Material label required?: YES			Hazardous Waste label required?: YES	
Waste Generation Process: MATERIAL OFF SPECIFICATION, EXCEEDED SHELF LIFE, IN DAMAGED OR OPEN CONTAINERS.				
Waste Class: HAZARDOUS WASTE			Required Container: STEEL / POLY	
EPA Waste Numbers U223,D003				
Special Handling & Instructions: SPECIAL NOTE: FIREX, (PART A), EPA WASTE CODE U223, IS NOT AUTHORIZED FOR STORAGE AT THE HWSF. SPECIAL ARRANGEMENTS MUST BE MADE FOR STORAGE AND DISPOSAL. UHC:NONE				
Remarks IF MATERIAL IS INGESTED, IMMEDIATELY CONTACT A PHYSICIAN OR THE POISON CONTROL CENTER. GHS06, GHS08				
For Environmental Department Use Only - - - - Material Composition				
Component		Percent	Parts Per Million	
1. CASTOR OIL, SULFONATED		60-100%	600000-1000000ppm	
2. TOLUENE DIISOCYANATE		5-10%	50000-100000ppm	
3.		%	ppm	
4.		%	ppm	
5.		%	ppm	
Physical State: LIQUID	Waste Water: NO	Toxic: YES	Dioxin Listed: NO	
Corrosive: NO	pH: N/A	Reactive: YES	Flash Point: 430	
High TOC:	Low TOC :	Land Ban: YES	Flammable: NO	
Reason for Classification: TOLUENE DIISOCYANATE, CAS #26471-62-5 IS A "U" LISTED WASTE				
Treatment Standards: 40 CFR 261		CAS# 26471-62-5	Generation Code: G11	
Shipping Information				
DOT Shipping Name: UN2206, WASTE ISOCYANATES, NOS (M-TOLUENE DIISOCYANATE) 6.1, PGIII, U223,D003				
HAZ Class: 6.1	Reportable Quantity: 100 LBS.		Emergency Response Guide #: 155	
EPA Waste Numbers: U223,D003				
Certification: I certify that the above named materials are the only compounds included in the waste stream described and no other substance is present.		Prepared by _____ Subase Env. Rep Signed and Dated Copy On File ____ Review/Signature_____		