

610	Subase Kings Bay, Georgia		Waste Information Document (WID)	
As of 5/4/2021		WID Number 5006 - 610		
Waste Description: EPOXY RESINS, UNCURED				
Waste Material label required?: YES		Hazardous Waste label required?: NO		
Waste Generation Process: EXPIRED SHELF LIFE, MATERIAL IN DAMAGED OR OPENED CONTAINERS. WID COVERS UNCURED EPOXY RESINS WITH NO LISTED SOLVENTS OR TOXIC METALS, AND FLASH POINTS ABOVE 140 F.				
Waste Class: NON HAZARDOUS WASTE		Required Container: STEEL / POLY		
EPA Waste Numbers NONE				
Special Handling & Instructions:				
Remarks				
For Environmental Department Use Only - - - - Material Composition				
Component		Percent		Parts Per Million
1. EPICHLOROHYDRIN-4,4'ISOPROPYLIDENE DIPHENOL RESIN		40-50%		400000-500000ppm
2. QUARTZ (SIO2)		20-30%		200000-300000ppm
3. UNKNOWN NATURALLY OCCURING SUBSTANCES		10-20%		100000-200000ppm
4. TALC		5-10%		50000-100000ppm
5. TREATED FUMED SILICA		1-5%		10000-50000ppm
Physical State: LIQUID	Waste Water: NO	Toxic: NO		Dioxin Listed: NO
Corrosive: NO	pH: N/A	Reactive: NO		Flash Point: 480 F.
High TOC:	Low TOC :	Land Ban: NO		Flammable: NO
Reason for Classification: NON LISTED, NON CHARACTERISTIC				
Treatment Standards: 40 CFR 261		CAS# SOLUTION	Generation Code: G11	
Shipping Information				
DOT Shipping Name: NON REGULATED LIQUID				
HAZ Class: NON REGULATED	Reportable Quantity: N/A LBS.		Emergency Response Guide #: N/A	
EPA Waste Numbers: NONE				
Certification: I certify that the above named materials are the only compounds included in the waste stream described and no other substance is present.		<div style="display: flex; justify-content: space-between;"> <div> Prepared by _____ Signed and Dated Copy On File ____ </div> <div> Subase Env. Rep _____ Review/Signature_____ </div> </div>		