714	4 Subase Kings Bay, Georgia				Waste Information Document (WID)			
As of 2/15/2018					WID Number 3077 - 714			
Waste De	escription: CHLOR	IDE TITRA	ATOR					
Waste Material label required?: YES					Hazardous Waste label required?: YES			
	eneration Process: E SNATED WITH SIL			F LIFE	ITEM. PLASTIC	STRIP W	ITH A COLUMN	
Waste Class: HAZARDOUS WASTE				F	Required Container: STEEL / POLY			
EPA Waste Numbers D007,D011								
Special I	Handling & Instruction	ons: UHC: N	NONE					
Remarks GHS07								
For Environmental Department Use Only Material Composition								
Component					Percent		Parts Per Million	
1. SILVER DICHROMATE					20%		200000 ppm	
2. PLASTIC					80%		800000 ppm	
3. 4.					%		ppm	
5.					%		ppm	
Physical State: SOLID Waste Water: NO				Т	Toxic: YES		ppm Dioxin Listed: NO	
-	Corrosive: NO pH: N/A				Reactive: NO		Flash Point: N/A	
	High TOC: Low TOC:				Land Ban: YES		Flammable: NO	
Reason for Classification: CONTAINS SILVER DICHROMATE								
Treatment Standards: 40 CFR 261				CAS#	CAS# MIXTURE		Generation Code: G11	
Shipping Information DOT Shipping Name: UN3077, HAZARDOUS WASTE SOLID NOS (SILVER, CHROMIUM) 9, PGIII, D007, D011								
HAZ Class: HAZARDOUS WASTE Reportable Quantity:					1 LBS.	Emergen	cy Response Guide #: 171	
EPA Was	ste Numbers: D007,I	D011						
Certification: I certify that the above named materials are the only compounds included in the waste stream described and no other substance is present. Prepared by Subase Env. Rep Signed and Dated Copy On File Review/Signature								