744	Subase Kings Bay, Georgia				Waste Information Document (WID)		
As of 11/19/2024				WID Number 1044 - 744			
Waste De	escription: FIRE EX	KTINGUIS	HERS (PRESS)	URIZE	D DRY AGENT O	NLY)	
Waste M	Iaterial label require	d?: YES	Hazardous Was	Hazardous Waste label required?: NO			
	eneration Process: F INING: PKP OR O				Y CHARGED OR I	EMPTY FI	RE EXTINGUISHERS
Waste Class: NON HAZARDOUS WASTE					Required Container: STEEL		
EPA Wa	ste Numbers NONE	E					
ETC)	Handling & Instruction	ons: TURN	IN EXTINGUI	ISHER:	S FROM NON-FA	CILITY (\	VEHICLE/EQUIPMENT,
	For E	nvironmei	ntal Departmen	nt Use (Only Mater	ial Compo	osition
Component				Percent		Parts Per Million	
1. POTASSIUM CARBONATE				80%		800000ppm	
2. CALCIUM CARBONATE					10%		100000ppm
3. MICA					5%		50000ppm
4. CLAY				5%		50000ppm	
5.				%		ppm	
Physical	Physical State: SOLID Waste Water: NO				Toxic: NO		Dioxin Listed: NO
Corrosiv	orrosive: NO pH: N/A]	Reactive: NO		Flash Point: N/A
High TOC: Low TOC:				Land Ban: NO		Flammable: NO	
Reason f	or Classification: NO	ON LISTE	D, NON CHAR	ACTE	RISTIC		
Treatment Standards: 40 CFR 261				CAS# MIXTURE		Generation Code: G09	
					ormation		
DOT Shi	pping Name: UN10-	44, FIRE E	EXTINGUISHE	RS, CC	ONTAINING COM	PRESSED	GAS, 2.2,
HAZ Class: 2.2			Reportable Quantity: N/A		N/A LBS.	Emergen	cy Response Guide #: 126
EPA Wa	ste Numbers: NONE						
are the or	tion: I certify that the nly compounds inclu- l and no other substa	ded in the	waste stream	Signe	Prepared by d and Dated Copy	 On File	Subase Env. Rep Review/Signature