973I Subase Kings Bay, Georgia			Waste Information Document (WID)			
As of 3/22/2018 WID Number 3077 - 973I						
Waste Description: ORDNA AFT	ANCE - UNSERVICEABL	E FLEX	IBLE LINEAR SI	HAPED C	CHARGE, FIRST STAGE	
Waste Material label required?: YES			Hazardous Waste label required?: YES			
Waste Generation Process: USERVICE, BUILDUP OR D						
Waste Class: HAZARDOUS WASTE		Required Container: STEEL/WOOD				
EPA Waste Numbers D003		'				
Special Handling & Instruction D059627, VOL. 2, PT. CON CONTAINER FOLLOWING Remarks GHS01	TACT EOD FOR PROPER					
For E	nvironmental Departmen	ıt Use Oı	nlv Materi	ial Comp	osition	
Component			Percent		Parts Per Million	
FLEXIBLE LINEAR SHAPED CHARGE			100%		1000000 ppm	
2. (RDX)			%		ppm	
3.			%		ppm	
4.			%		ppm	
5.			%		ppm	
Physical State: SOLID	Waste Water: NO		oxic: NO		Dioxin Listed: NO	
Corrosive: NO	pH: N/A	Re	Reactive: YES		Flash Point: N/A	
High TOC:	Low TOC:		Land Ban: YES		Flammable: YES	
Reason for Classification: E.	XPLOSIVE WASTE (REA	(CTIVE)				
Treatment Standards: 40 CFR 261		CAS# MIXTURE Genera		ation Code: M04		
	Shippi	ing Infor	mation			
DOT Shipping Name: CHA	RGES SHAPED FLEXIBL	E LINE	AR (150)			
HAZ Class: HAZARDOUS WASTE Reportable Quan			entity: 100 LBS. Emergency Response Guide #: 112			
EPA Waste Numbers: D003						
Certification: I certify that the are the only compounds includescribed and no other substates		Prepared by and Dated Copy (— On File _	Subase Env. Rep Review/Signature		